


急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	令和5年度
松戸市東平賀	

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-18388.57	9144.85				R1	-18386.71	9100.11			
Y2	-18385.23	9134.27				R2	-18386.43	9093.02			
Y3	-18379.35	9119.98				R3	-18391.60	9083.84			
Y4	-18392.63	9118.17				R4	-18391.47	9075.47			
Y5	-18397.98	9117.44				R5	-18396.13	9075.10			
Y6	-18405.01	9116.48				R6	-18396.19	9075.09			
Y7	-18407.89	9116.08				R7	-18397.11	9084.84			
Y8	-18412.93	9130.91				R8	-18392.25	9094.39			
Y9	-18413.73	9141.36				R9	-18390.59	9100.96			
Y10	-18407.17	9142.27				R10	-18390.49	9100.94			
Y11	-18403.82	9142.74									
Y12	-18398.47	9143.48									
Y13	-18380.82	9098.81									
Y14	-18380.59	9091.65									
Y15	-18385.96	9082.82									
Y16	-18386.22	9075.88									
Y17	-18396.13	9075.10									
Y18	-18396.19	9075.09									
Y19	-18403.76	9074.49									
Y20	-18404.14	9074.46									
Y21	-18413.73	9073.70									
Y22	-18413.52	9087.80									
Y23	-18408.33	9098.16									
Y24	-18404.64	9104.07									
Y25	-18397.50	9102.49									
Y26	-18394.88	9101.91									
Y27	-18390.59	9100.96									
Y28	-18390.49	9100.94									

平面直角座標系：第Ⅸ系(測地成果2011)