急傾斜地の崩壊区域調書

意情斜地の位置 箇所書号 17-037(22)46 箇所名 <i>兩化思</i> 1 所在地 1822年 17-12 17-12 17-12 17-13	様式5-4 危害のおそれのある	る工地寺の座標位で	直凶		-111		調査	年度	2023
Y10 Y10 Y10 Y113 Y13 Y14 Y15 Y16 Y15 Y16 Y17 Y16 Y17 Y16 Y17 Y16 Y17 Y16 Y17 Y17 Y17 Y18 Y18 Y18 Y18 Y18 Y18 Y18 Y18 Y18 Y18	急傾斜地の位置	箇所番号	II -031K2146	箇所名	南花島1	所在地	松戸市南花島3丁目		
1:500 0 10 20 m	○記憶料型の位置	固加番号	П-031К2146	Y11 Y10	Y3	Y12	3 14 15		N N
1:500 0 10 20 m									
0 10 20 m	1:500								
	0 10	20 m							

急傾斜地の崩壊区域調書

南花島1

様式5-5 危害のおそれのある土地の座標一覧

II-031K2146

箇所名

急傾斜地の位置 箇所番号

調査年度

平面直角座標系:第IX系(測地成果2011)

所在地

2023

松戸市南花島3丁目

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
也点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-23388.22	7088.61									
Y2	-23396.21	7087.42									
Y3	-23392.03	7075.68									
Y4	-23404.57	7076.89									
Y5	-23403.36	7069.07									
Y6	-23403.04	7067.00									
Y7	-23402.75	7065.13									
Y8	-23402.35	7062.49									
Y9	-23401.23	7055.25									
Y10	-23373.53	7059.34									
Y11	-23370.45	7063.09									
Y12	-23374.55	7090.64									
Y13	-23382.54	7089.45									
Y14	-23384.44	7089.17									
Y15	-23386.32	7088.89									
Y16	-23388.22	7088.61									
					·						