
急傾斜地の崩壊区域調書



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 2024

| 危害のおそれのある土地の座標 | | | | | | 著しい危害のおそれのある土地の座標 | | | | | |
|----------------|-----------|----------|------|------|------|-------------------|------|------|----------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| Y-1 | -13782.54 | 13129.86 | | | | | | | | | |
| Y-2 | -13786.75 | 13130.88 | | | | | | | | | |
| Y-3 | -13791.13 | 13131.94 | | | | | | | | | |
| Y-4 | -13793.18 | 13132.44 | | | | | | | | | |
| Y-5 | -13800.84 | 13134.31 | | | | | | | | | |
| Y-6 | -13805.45 | 13120.28 | | | | | | | | | |
| Y-7 | -13809.78 | 13094.29 | | | | | | | | | |
| Y-8 | -13787.81 | 13084.51 | | | | | | | | | |
| Y-9 | -13785.88 | 13090.22 | | | | | | | | | |
| Y-10 | -13784.61 | 13093.98 | | | | | | | | | |
| Y-11 | -13783.17 | 13098.24 | | | | | | | | | |
| Y-12 | -13781.91 | 13101.96 | | | | | | | | | |
| Y-13 | -13779.97 | 13107.72 | | | | | | | | | |
| Y-14 | -13785.46 | 13107.13 | | | | | | | | | |
| Y-15 | -13779.59 | 13113.67 | | | | | | | | | |
| Y-16 | -13777.03 | 13128.52 | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |