


急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	令和5年度
------	-------

急傾斜地の位置	箇所番号	II-053K2015	箇所名	根古谷4	所在地	八街市根古谷
---------	------	-------------	-----	------	-----	--------



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 令和5年度

急傾斜地の位置		箇所番号	II-053K2015		箇所名	根古谷4		所在地	八街市根古谷		
危害のおそれのある土地の座標						著しい危害のおそれのある土地の座標					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-40326.13	38415.12				R-1	-40345.12	38420.37			
Y-2	-40334.31	38419.42				R-2	-40348.39	38425.79			
Y-3	-40333.92	38423.76				R-3	-40347.88	38427.80			
Y-4	-40337.35	38426.74				R-4	-40348.06	38428.62			
Y-5	-40339.26	38426.58				R-5	-40341.12	38439.68			
Y-6	-40336.73	38432.57				R-6	-40334.07	38447.01			
Y-7	-40331.40	38442.03				R-7	-40336.13	38450.84			
Y-8	-40331.68	38442.56				R-8	-40345.14	38446.18			
Y-9	-40336.13	38450.84				R-9	-40354.54	38438.53			
Y-10	-40338.49	38455.24				R-10	-40360.03	38431.39			
Y-11	-40338.73	38455.68				R-11	-40360.33	38424.76			
Y-12	-40343.23	38464.05				R-12	-40357.27	38416.82			
Y-13	-40353.02	38458.94				R-13	-40353.96	38408.94			
Y-14	-40363.35	38452.03				R-14	-40341.30	38404.39			
Y-15	-40375.32	38435.90				R-15	-40333.19	38397.73			
Y-16	-40376.21	38423.39				R-16	-40333.10	38398.15			
Y-17	-40372.90	38413.71				R-17	-40332.10	38401.37			
Y-18	-40367.68	38402.91				R-18	-40331.77	38402.40			
Y-19	-40351.07	38390.91				R-19	-40329.81	38407.22			
Y-20	-40336.98	38380.55				R-20	-40337.94	38412.45			
Y-21	-40334.83	38390.31				R-21	-40344.43	38413.81			
Y-22	-40333.10	38398.15									
Y-23	-40332.10	38401.37									
Y-24	-40331.77	38402.40									
Y-25	-40329.47	38408.08									

平面直角座標系:第Ⅸ系(測地成果2011)

平面直角座標系: 第IX系(測地成果2011)