急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度

平成25年度

急傾斜地の位置	箇所番号	II -060040	箇所名	東吉田7	所在地	八街市東吉田

	危	害のおそれの	ある土地の座	標	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	41844.51	-39346.61			
Y-2	41823.84	-39339.20			
Y-3	41823.38	-39334.06			
Y-4	41825.02	-39330.63			
Y-5	41831.82	-39313.20			
Y-6	41844.13	-39304.48			
Y-7	41863.35	-39297.35			
Y-8	41881.05	-39316.68			
Y-9	41859.94	-39323.09			
Y-10	41859.74	-39324.58			
Y-11	41861.98	-39327.46			
Y-12	41852.84	-39337.45			
Y-13	41848.10	-39341.03			

<u> 木口田「</u>		771711	, / (国中)/	<i>С</i> Д Д	
	 著しし	・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	ιのある土地の	 D座標	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R-1	41838.97	-39344.62			
R-2	41835.10	-39343.23			
R-3	41837.12	-39336.08			
R-4	41842.43	-39325.44			
R-5	41853.14	-39316.08			
R-6	41861.20	-39313.54			
R-7	41866.69	-39321.04			
R-8	41862.53	-39322.30			
R-9	41860.24	-39320.76			
R-10	41857.17	-39321.27			
R-11	41847.81	-39331.64			
R-12	41840.62	-39337.65			