


急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度	平成24年度
------	--------

急傾斜地の位置	箇所番号	II-070254	箇所名	北羽鳥14	所在地	成田市北羽鳥
---------	------	-----------	-----	-------	-----	--------



# 急傾斜地の崩壊区域調書

様式5ー5 危害のおそれのある土地等の座標一覧

調査年度 平成24年度

急傾斜地の位置	箇所番号	II-070254		箇所名	北羽鳥14	所在地	成田市北羽鳥
---------	------	-----------	--	-----	-------	-----	--------

危害の恐れのある土地の座標					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-16785.28	41599.66	Y-29	-16818.11	41652.25
Y-2	-16781.31	41613.76	Y-30	-16823.58	41633.72
Y-3	-16781.81	41629.74	Y-31	-16809.79	41619.78
Y-4	-16779.02	41636.99	Y-32	-16813.48	41606.85
Y-5	-16775.34	41650.09	Y-33	-16804.65	41604.60
Y-6	-16775.46	41674.46	Y-34	-16794.97	41602.14
Y-7	-16782.30	41686.54	Y-35	-16557.19	41713.72
Y-8	-16785.29	41689.32	Y-36	-16557.06	41723.72
Y-9	-16776.87	41685.57	Y-37	-16556.93	41734.17
Y-10	-16770.14	41684.51	Y-38	-16556.86	41739.32
Y-11	-16763.84	41690.39	Y-39	-16571.78	41748.49
Y-12	-16750.25	41682.33	Y-40	-16588.44	41752.17
Y-13	-16730.23	41682.48	Y-41	-16608.04	41743.73
Y-14	-16730.22	41682.48	Y-42	-16608.16	41740.31
Y-15	-16703.67	41702.07	Y-43	-16608.69	41724.59
Y-16	-16704.84	41712.00	Y-44	-16608.60	41716.34
Y-17	-16706.98	41730.13	Y-45	-16590.26	41722.43
Y-18	-16707.46	41734.24	Y-46	-16572.34	41718.30
Y-19	-16732.41	41762.79			
Y-20	-16732.42	41762.79			
Y-21	-16756.82	41762.17			
Y-22	-16769.73	41757.21			
Y-23	-16794.29	41746.76			
Y-24	-16799.74	41743.77			
Y-25	-16828.38	41718.97			
Y-26	-16825.13	41689.87			
Y-27	-16815.55	41673.30			
Y-28	-16817.24	41652.41			

著しい危害の恐れのある土地の座標					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R-1	-16730.28	41698.49			
R-2	-16705.66	41718.93			
R-3	-16705.92	41721.14			
R-4	-16706.60	41726.95			
R-5	-16731.13	41729.27			
R-6	-16730.73	41718.87			
R-7	-16730.31	41707.75			
R-8	-16556.99	41729.32			
R-9	-16556.93	41733.90			
R-10	-16571.93	41740.34			
R-11	-16588.83	41745.80			
R-12	-16608.23	41738.25			
R-13	-16608.41	41733.06			
R-14	-16589.23	41739.18			
R-15	-16572.07	41733.15			