
急傾斜地の崩壊区域調書



急傾斜地の崩壊区域調書

下花輪 I

所在地

箇 所 名

様式5-5 危害のおそれのある土地の座標一覧

II -1020

急傾斜地の位置

調査年度 平成22年度 流山市下花輪寺下

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記 号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y−1	6282.25	-14442.80				R−1	6287.84	-14444.15			
Y-2	6277.00	-14452.58				R-2	6284.57	-14454.75			
Y-3	6264.44	-14476.24				R-3	6273.31	-14475.41			
Y-4	6272.93	-14482.82				R-4	6281.67	-14482.60			
Y-5	6265.60	-14495.01				R-5	6273.87	-14494.05			
Y-6	6268.61	-14506.82				R-6	6277.41	-14506.44			
Y-7	6267.99	-14526.21				R-7	6277.06	-14526.18			
Y-8	6267.28	-14545.86				R-8	6274.58	-14545.75			
Y-9	6263.14	-14564.94				R-9	6273.38	-14564.46			
Y-10	6264.99	-14581.76				R-10	6273.85	-14580.33			
Y-11	6270.40	-14598.88				R-11	6277.90	-14598.58			
Y-12	6271.43	-14615.85				R-12	6279.03	-14615.87			
Y-13	6271.44	-14615.91				R-13	6279.03	-14615.92			
Y-14	6271.75	-14625.97									
Y-15	6284.40	-14637.52									
Y-16	6283.87	-14644.63									
Y-17	6281.60	-14667.82									
Y-18	6280.55	-14677.38									