
急傾斜地の崩壊区域調書



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧 調査年度 *平成29年度* 急傾斜地の位置 箇所番号 II-1056 箇所 名 泉1 所在地 柏市泉

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y−1	-17443.58	19608.81				R−1	-17451.08	19609.94			
Y-2	-17447.01	19607.48				R−2	-17455.19	19608.54			
Y-3	-17444.67	19596.19				R-3	-17450.85	19595.18			
Y-4	-17442.07	19593.36				R−4	-17446.90	19590.99			
Y-5	-17451.26	19588.85				R-5	-17451.26	19588.85			
Y-6	-17457.37	19585.85				R-6	-17451.40	19588.78			
Y-7	-17466.34	19581.44				R-7	-17456.95	19594.19			
Y-8	-17472.81	19591.59				R-8	-17462.99	19609.56			
Y-9	-17478.08	19611.52				R-9	-17459.22	19611.17			
Y-10	-17477.42	19613.91				R-10	-17456.59	19610.77			
Y-11	-17467.54	19612.42				R-11	-17454.62	19610.48			
Y-12	-17460.06	19611.30									
Y-13	-17456.59	19610.77									
Y-14	-17454.62	19610.48									
Y-15	-17449.03	19609.63									
		T)	İ					The state of the s			
		T)	İ					The state of the s			
		T)	İ					The state of the s			