急傾斜地の崩壊区域調書

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度 令和5年度

急傾斜地の位置	箇所番号	II −123K2083	箇所名	<i>小谷松5</i>	所在地	夷隅郡大多喜町小谷松

	fi	色害のおそれの	ある土地の座標	票	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-80,856.19	37,687.31	Y-28	-80,862.54	37,677.01
Y-2	-80,828.81	37,673.67			
Y-3	-80,810.18	37,658.03			
Y-4	-80,783.47	37,630.63			
Y-5	-80,780.66	37,608.95			
Y-6	-80,784.83	37,572.98			
Y-7	-80,820.47	37,585.09			
Y-8	-80,832.17	37,589.07			
Y-9	-80,847.82	37,594.39			
Y-10	-80,856.09	37,596.24			
Y-11	-80,861.64	37,596.44			
Y-12	-80,864.78	37,596.00			
Y-13	-80,868.41	37,595.50			
Y-14	-80,871.38	37,595.29			
Y−15	-80,874.73	37,595.45			
Y−16	-80,874.94	37,595.91			
Y−17	-80,875.01	37,595.96			
Y-18	-80,880.70	37,600.50			
Y−19	-80,895.13	37,610.85			
Y-20	-80,894.91	37,619.82			
Y-21	-80,894.02	37,625.86			
Y-22	-80,892.93	37,629.60	_		_
Y-23	-80,892.90	37,629.70			
Y-24	-80,890.69	37,633.79			
Y−25	-80,887.51	37,637.95			
Y-26	-80,883.97	37,642.25			
Y-27	-80,878.76	37,650.69			

	 著し	い危害のおそれ	このある土地の ₈	············· 座標	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R−1	-80,873.33	37,659.51			
R-2	-80,855.13	37,646.56			
R-3	-80,839.98	37,634.78			
R-4	-80,821.10	37,619.57			
R-5	-80,819.53	37,604.90			
R-6	-80,821.72	37,585.52			
R−7	-80,832.17	37,589.07			
R-8	-80,847.82	37,594.39			
R-9	-80,856.09	37,596.24			
R-10	-80,858.86	37,596.34			
R-11	-80,858.98	37,598.98			
R-12	-80,859.24	37,600.83			
R-13	-80,868.53	37,612.05			
R-14	-80,881.71	37,621.15			
R−15	-80,889.98	37,634.72			
R-16	-80,887.51	37,637.95			
R-17	-80,883.97	37,642.25			
R-18	-80,878.76	37,650.69			

平面直角座標系:第区系(測地成果2011)