急 傾 斜 地 の 崩 壊 区 域 調 書

様式5-4 危害のおそれのな		禁位置 図				調査年度
急傾斜地の位置	箇所番号	<i>II −123K2100−1</i>	箇所名	小苗3	所在地	夷隅郡大多喜町小苗
			Y-1	R-24 R-2 R-23 R-3 R-22	Y-25 Y-24 R-21 Y-23 Y-22 Y-21 R-13 Y-20 Y-15 R-18 Y-19	R 例

様式5-5 危害のおそれのある土地等の座標一覧


急傾斜地の位置 箇所番号 *II-123K2100-1* 箇所名 小苗3 小苗3 所在地 夷隅郡大多喜町小苗

	f	色害のおそれの	ある土地の座	標	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y-1	-81,983.37	34,424.77	Y-28	-81,953.20	34,469.71
Y-2	-81,996.31	34,437.94	Y-29	-81,956.60	34,464.63
Y-3	-82,010.71	34,442.51	Y-30	-81,958.77	34,461.41
Y-4	-82,030.84	34,451.19	Y-31	-81,966.05	34,450.57
Y-5	-82,048.85	34,451.39	Y-32	-81,967.48	34,448.44
Y-6	-82,045.25	34,461.46			
Y-7	-82,043.22	34,468.68			
Y-8	-82,042.03	34,475.24			
Y-9	-82,041.62	34,480.24			
Y-10	-82,041.71	34,484.14			
Y-11	-82,042.20	34,487.41			
Y-12	-82,042.99	34,490.04			
Y-13	-82,044.48	34,492.82			
Y-14	-82,046.00	34,494.62			
Y-15	-82,047.83	34,496.20			
Y-16	-82,050.21	34,497.77			
Y-17	-82,054.98	34,499.84			
Y-18	-82,054.41	34,500.40			
Y-19	-82,048.83	34,505.86			
Y-20	-82,037.09	34,517.36			
Y-21	-82,031.31	34,523.02			
Y-22	-82,029.95	34,524.36			
Y-23	-82,021.75	34,517.34			
Y-24	-82,010.15	34,508.70			
Y-25	-81,997.17	34,500.39			
Y-26	-81,981.49	34,490.58			
Y-27	-81,966.18	34,481.53			

著しい危害のおそれのある土地の座標						
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	
R−1	-81,970.64	34,443.74				
R-2	-81,985.06	34,454.22				
R-3	-81,999.95	34,460.20				
R-4	-82,018.68	34,468.97				
R-5	-82,038.63	34,476.02				
R-6	-82,041.70	34,479.29				
R-7	-82,041.62	34,480.24				
R-8	-82,041.71	34,484.14				
R-9	-82,042.20	34,487.41				
R-10	-82,042.99	34,490.04				
R-11	-82,044.48	34,492.82				
R-12	-82,046.00	34,494.62				
R-13	-82,047.83	34,496.20				
R-14	-82,050.21	34,497.77				
R−15	-82,054.59	34,499.67				
R-16	-82,054.67	34,500.14				
R−17	-82,054.41	34,500.40				
R-18	-82,048.83	34,505.86				
R-19	-82,039.37	34,515.13				
R-20	-82,032.62	34,508.34				
R-21	-82,020.12	34,497.05				
R-22	-82,006.27	34,487.10				
R-23	-81,989.57	34,477.29				
R-24	-81,974.77	34,469.10				
R-25	-81,961.11	34,457.92				
R-26	-81,966.05	34,450.57				
R-27	-81,967.48	34,448.44				

平面直角座標系:第区系(測地成果2011)

急 傾 斜 地 の 崩 壊 区 域 調 書




様式5-5 危害のおそれのある土地等の座標一覧

急傾斜地の位置	箇所番号	II −123K2100−2	箇所名	小苗3	所在地	夷隅郡大多喜町小苗

	fi	色害のおそれの	ある土地の座標	票	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y−1	-82,068.86	34,499.21			
Y-2	-82,069.43	34,499.06			
Y-3	-82,079.33	34,495.55			
Y-4	-82,093.23	34,489.66			
Y-5	-82,093.68	34,491.07			
Y-6	-82,096.67	34,500.26			
Y-7	-82,099.00	34,507.42			
Y-8	-82,099.76	34,509.77			
Y-9	-82,087.97	34,514.00			
Y-10	-82,076.09	34,522.16			
Y-11	-82,075.11	34,519.05			
Y-12	-82,073.08	34,512.62			
Y-13	-82,069.36	34,500.82			

	著し	い危害のおそれ	ıのある土地の!	· · · · · · · · · · · · · · · · · · ·	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R−1	-82,068.86	34,499.21			
R-2	-82,069.43	34,499.06			
R-3	-82,079.33	34,495.55			
R-4	-82,093.23	34,489.66			
R-5	-82,093.68	34,491.07			
R-6	-82,095.94	34,497.99			
R−7	-82,084.00	34,502.69			
R-8	-82,072.26	34,510.01			
R-9	-82,069.36	34,500.82			



様式5-5 危害のおそれのある土地等の座標一覧

調査年度 令和5年度

ᄼᅜᄼᆘᄼ	佐記 平口	TI 1001/0100 0	佐 記 夕	./. // 0		<i> </i>
急傾斜地の位置	1 街所番号	∏-123K2100-3	箇 所名	/ 小 前3	所在地	夷隅郡大多喜町小苗
101X111011 ILE		11 120112100 0		Э ШО	//I IX-0	

	fi	色害のおそれの	ある土地の座標	票	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y−1	-81,986.46	34,358.03			
Y-2	-81,990.71	34,376.06			
Y-3	-81,990.50	34,392.87			
Y-4	-81,976.99	34,402.07			
Y-5	-81,975.48	34,400.81			
Y-6	-81,969.29	34,395.68			
Y-7	-81,965.45	34,392.49			
Y-8	-81,962.94	34,390.42			
Y-9	-81,957.75	34,386.11			
Y-10	-81,960.08	34,386.93			
Y-11	-81,960.65	34,384.41			
Y−12	-81,956.87	34,366.58			
Y-13	-81,957.29	34,366.46			
Y-14	-81,966.48	34,363.80			
Y−15	-81,974.16	34,361.58			
Y-16	-81,980.41	34,359.78			

	著し	い危害のおそれ	このある土地のE	 	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R−1	-81,979.64	34,360.00			
R−2	-81,983.20	34,378.15			
R-3	-81,984.06	34,391.61			
R-4	-81,972.64	34,398.45			
R-5	-81,969.29	34,395.68			
R-6	-81,977.26	34,390.29			
R−7	-81,975.67	34,380.24			
R-8	-81,972.48	34,362.07			
R-9	-81,974.16	34,361.58			