

急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2023

急傾斜地の位置

箇所番号


II-123K2227

箇所名

平沢29

所在地

夷隅郡大多喜町平沢



1:1,500

0 30 60 m

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2023
------	------

急傾斜地の位置	箇所番号	Ⅱ-123K2227	箇所名	平沢29	所在地	夷隅郡大多喜町平沢
---------	------	------------	-----	------	-----	-----------

危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-86489.60	36470.25				R1	-86476.85	36474.93			
Y2	-86495.73	36483.56				R2	-86480.46	36484.24			
Y3	-86498.75	36482.67				R3	-86486.97	36490.31			
Y4	-86500.65	36482.56				R4	-86499.85	36496.01			
Y5	-86502.88	36483.57				R5	-86507.21	36499.45			
Y6	-86512.60	36490.03				R6	-86512.92	36513.71			
Y7	-86520.31	36496.26				R7	-86506.14	36514.97			
Y8	-86522.32	36498.60				R8	-86501.29	36515.86			
Y9	-86526.22	36506.16				R9	-86473.72	36520.95			
Y10	-86527.89	36508.28				R10	-86444.48	36525.36			
Y11	-86531.39	36510.27				R11	-86444.08	36524.00			
Y12	-86531.46	36510.30				R12	-86443.19	36522.68			
Y13	-86506.14	36514.97				R13	-86442.18	36521.25			
Y14	-86501.29	36515.86				R14	-86435.67	36509.33			
Y15	-86473.72	36520.95				R15	-86424.06	36496.74			
Y16	-86438.95	36526.20				R16	-86424.26	36496.65			
Y17	-86433.08	36527.08				R17	-86438.71	36489.93			
Y18	-86429.06	36527.69				R18	-86459.93	36481.14			
Y19	-86428.76	36526.49				R19	-86466.33	36478.79			
Y20	-86428.38	36525.27				R20	-86472.20	36476.64			
Y21	-86428.09	36524.08									
Y22	-86423.57	36516.18									
Y23	-86411.34	36502.95									
Y24	-86417.54	36499.93									
Y25	-86420.33	36498.57									
Y26	-86424.26	36496.65									
Y27	-86438.71	36489.93									
Y28	-86459.93	36481.14									
Y29	-86466.33	36478.79									
Y30	-86472.20	36476.64									

平面直角座標系: 第Ⅸ系(測地成果2011)