
急傾斜地の崩壊区域調書



急傾斜地の崩壊区域調書

松虫4

様式5-5 危害のおそれのある土地等の座標一覧

調査年度

平成23年度

急傾斜地の位置	箇所	番号		II -1264	箇所	名			
	危害の恐れのある土地の座標								
地点記号	X(m)	Y(m)	地点記号	X(m)	Υ(1	m)		
Y-1	34442.70	-22970).82						
Y-2	34452.98	-22968	3.08						
Y-3	34462.44	-22967	7.48						
Y-4	34464.75	-22970).29						
Y-5	34468.79	-22975	5.20						
Y-6	34469.79	-22976	3.41						
Y-7	34471.91	-22979	00.0						
Y-8	34474.36	-22982	2.28						
Y-9	34480.40	-22990	0.36						
Y-10	34483.57	-22994	1.61						
Y-11	34464.58	-23007	7.19						
Y-12	34449.79	-23012	2.28						
Y-13	34446.66	-23000).76						
Y-14	34444.41	-22992	2.44						
Y-15	34443.68	-22989	9.75						
Y-16	34443.36	-22988	3.56						
Y-17	34443.07	-22986	3.73						
Y-18	34442.89	-22984	1.57						
Y-19	34442.84	-22980	0.82						
Y-20	34442.82	-22979	9.21						

		· · · · · · ·			
	著し	 い危害の恐れ	 のある土地の	 座標	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R−1	34443.06	-22986.56			
R-2	34457.86	-22982.34			
R−3	34472.47	-22979.75			
R-4	34474.36	-22982.28			
R-5	34478.19	-22987.40			
R-6	34461.17	-22994.47			
R-7	34446.40	-22999.77			
R-8	34444.41	-22992.44			
R-9	34443.68	-22989.75			
R-10	34443.36	-22988.56			
R-11	34443.07	-22986.73			

所在地 印西市松虫