

急傾斜地の崩壊区域調査

様式5-4 危害のおそれのある土地等の座標位置図

調査年度

2023

急傾斜地の位置

箇所番号


II-132K2007

箇所名

磯村1

所在地

鴨川市磯村、貝渚



1:1,000

0 25 50 m

急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧

調査年度	2023
所在地	鶴川市磯村、貝渚

急傾斜地の位置	箇所番号	Ⅱ-132K2007	箇所名	磯村1		所在地	鴨川市磯村、貝渚				
危害のおそれのある区域の座標(土砂災害警戒区域)						著しい危害のおそれのある区域の座標(土砂災害特別警戒区域)					
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
Y1	-100634.01	24726.50				R1	-100624.86	24716.45			
Y2	-100621.64	24736.78				R2	-100613.25	24730.32			
Y3	-100621.64	24736.78				R3	-100613.25	24730.32			
Y4	-100602.01	24745.97				R4	-100596.60	24741.64			
Y5	-100590.97	24752.97				R5	-100586.48	24749.15			
Y6	-100595.34	24763.12				R6	-100588.81	24758.96			
Y7	-100595.34	24763.12				R7	-100588.81	24758.96			
Y8	-100585.22	24778.02				R8	-100585.83	24757.05			
Y9	-100576.54	24770.41				R9	-100585.83	24757.05			
Y10	-100574.70	24768.78				R10	-100585.83	24757.05			
Y11	-100572.74	24767.07				R11	-100584.04	24755.91			
Y12	-100570.59	24765.18				R12	-100584.04	24755.91			
Y13	-100565.23	24760.48				R13	-100582.50	24754.93			
Y14	-100569.54	24746.67				R14	-100582.50	24754.93			
Y15	-100569.54	24746.67				R15	-100582.41	24745.68			
Y16	-100570.49	24735.53				R16	-100590.76	24736.97			
Y17	-100578.40	24725.32				R17	-100604.42	24723.74			
Y18	-100590.38	24716.94				R18	-100604.42	24723.74			
Y19	-100590.38	24716.94				R19	-100615.42	24704.81			
Y20	-100607.05	24690.84				R20	-100617.66	24708.55			
Y21	-100610.88	24697.24				R21	-100619.57	24710.65			
Y22	-100612.19	24699.42				R22	-100620.39	24711.54			
Y23	-100617.66	24708.55									
Y24	-100619.57	24710.65									
Y25	-100620.39	24711.54									

平面直角座標系：第Ⅸ区系(測地成果2011)