
急傾斜地の崩壊区域調書



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度

平成25年度

急傾斜地の位置 箇所番号 II-1423 箇所名 小林7 所在地 印西市小林、小林浅間

危害のおそれのある土地の座標								
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)			
Y-1	32687.31	-19064.18						
Y-2	32699.20	-19055.35						
Y-3	32716.10	-19048.95						
Y-4	32726.42	-19043.28						
Y-5	32733.78	-19036.47						
Y-6	32743.41	-19038.01						
Y-7	32762.76	-19054.45						
Y-8	32755.24	-19064.63						
Y-9	32745.09	-19069.04						
Y-10	32730.37	-19078.50						
Y-11	32720.55	-19085.68						
Y-12	32709.42	-19091.91						
Y-13	32710.88	-19095.76						
Y-14	32696.99	-19089.79						
Y-15	32684.36	-19093.56						
Y-16	32677.76	-19095.52						
Y-17	32673.57	-19079.74						

		77.12	*					
著しい危害のおそれのある土地の座標								
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)			
R-1	32698.77	-19078.55						
R-2	32709.73	-19070.32						
R-3	32723.39	-19064.06						
R-4	32736.12	-19056.65						
R-5	32744.19	-19050.12						
R-6	32755.14	-19047.98						
R-7	32758.59	-19050.90						
R-8	32750.08	-19057.86						
R-9	32740.78	-19063.08						
R-10	32727.05	-19071.64						
R-11	32715.51	-19078.52						
R-12	32704.39	-19085.59						
R-13	32696.63	-19089.64						
R-14	32691.37	-19091.47						
R-15	32686.36	-19085.23						