
## 急傾斜地の崩壊区域調書



## 急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地等の座標一覧

調査年度

平成28年度

急傾	斜地の位置	箇所番号	II -2436	箇所名		小池2		所在地	芝山町八	小池井戸作		
Г												T
	危害の恐れのある土地の座標					著しい危害の恐れのある土地の座標						
					,					, ,		ſ

地点記号	X(m)	Y(m)	ある土地の座標 地点記号	X(m)	Y(m)
			26 M BL 7	Λ(111/	1 (1117
Y-1		-34133.49			
Y-2	53417.48				
Y-3	53417.37				
Y-4	53395.70	-34157.71			
Y-5	53387.04	-34142.09			
Y-6	53388.85	-34124.11			
Y-7	53381.40	-34120.23			
Y-8	53376.57	-34119.95			
Y-9	53360.48	-34127.89			
Y-10	53353.40	-34092.32			
Y-11	53403.84	-34089.25			

7 1000		// II		1 10/1/ 11	
	 著し	い危害の恐れ	 のある土地の	 座標	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R-1	53403.11	-34119.92			
R-2	53406.36	-34137.26			
R-3	53404.62	-34153.19			
R-4	53401.07	-34154.98			
R-5	53396.57	-34139.71			
R-6	53397.88	-34121.46			
R-7	53386.76	-34112.83			
R-8	53375.18	-34111.19			
R-9	53358.18	-34116.32			
R-10	53356.23	-34106.53			
R-11	53392.90	-34104.34			