
急傾斜地の崩壊区域調書



急傾斜地の崩壊区域調書

様式5-5 危害のおそれのある土地の座標一覧 調査年度 *平成28年度* 急傾斜地の位置 箇所番号 *Ⅲ-1068* 箇所名 *片山4* 所在地 *柏市片山*

| 危害のおそれのある区域の座標(土砂災害警戒区域) | | | | | | 著しい危害のおそれのある区域の座標(土砂災害特別警戒区域) | | | | | |
|--------------------------|-----------|----------|------|------|------|-------------------------------|-----------|----------|------|------|------|
| 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) | 地点記号 | X(m) | Y(m) |
| Y−1 | -17210.30 | 20719.83 | | | | R−1 | -17219.71 | 20723.91 | | | |
| Y-2 | -17222.59 | 20703.46 | | | | R−2 | -17229.55 | 20712.63 | | | |
| Y-3 | -17246.09 | 20735.32 | | | | R−3 | -17237.87 | 20723.59 | | | |
| | | | | | | R-4 | -17230.62 | 20728.63 | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |