急傾斜地の崩壊区域調書

東吉田5

様式5-5 危害のおそれのある土地等の座標一覧

調査年度

平成25年度

急傾斜地の位置	箇所	番号	Ⅲ −108	37	箇所名	
		害のおそ	 れのある土地	の座標		
地点記 号	X(m)	Y(m)	地点記	号 X(m	n) Y(m)
Y-1	42280.26	-39370	.44			
Y-2	42295.88	-39337	.06			
Y-3	42309.93	-39343	.01			
Y-4	42309.93	-39343	.00			
Y-5	42318.35	-39345	.84			
Y-6	42331.31	-39350	.73			
Y-7	42339.62	-39360	.27			
Y-8	42348.63	-39369	.07			
Y-9	42331.59	-39383	.61			
Y-10	42324.20	-39376	.89			
Y-11	42318.20	-39379	.59			
Y-12	42305.49	-39381	.59			
Y-13	42288.60	-39376	.21			

жано		171 IL-C	1 1111/		
	 著しし	 \危害のおそれ	 ιのある土地の	 D座標	
地点記号	X(m)	Y(m)	地点記号	X(m)	Y(m)
R-1	42285.49	-39359.25			
R-2	42289.79	-39350.06			
R-3	42303.32				
R-4	42313.51				
R-5	42325.30	-39363.97			
R-6	42322.06	-39371.10			
R-7	42309.92	-39369.29			
R-8	42296.22	-39366.28			

所在地 八街市東吉田